

Harvey Booster Station Pump #2 Rebuild Addenda - 9/9/2020

- Information on the pump and motor shafts is in the inspection report. Per the inspection report, the motor drive shaft is in good shape and can be reused. Clean the motor drive shaft of grease and debris prior to install.
- The gap mentioned in the “Additional Notes” of the inspection report is part of the design of the pump and does not have to be addressed.
- True all wear surfaces on the three impellers.
- The color on the visible exterior parts of the pump head should be royal blue (or similar). The color on the non-visible portions of the pump does not need to be blue.
- The white exterior coating on the purchased pump bowls and suction bell is Carboline 891 with a vitreous enamel interior coating. These will not need additional coatings.
- Pre-bid meeting attendees: Kennedy Industries, Fluid Process Equipment, Peerless Midwest, Northern Pump & Well, and KSB Dubric.

Each end of the motor drive shaft shaft.

